Routing Options

Wiring diagrams for various signal routing options.

- HX Stomp - Wet Dry Wet
- Strymon Iridium - Wet Dry Wet
- Walrus ACS1 - Wet Dry Wet
- Kemper - Wet Dry Wet
- Dirty - Wet Dry Wet
- Clean - Wet Dry Wet
- Dual Delay - Wet Dry Wet
- Dirty - Wet Dry
- Clean - Wet Dry
- Parallel - Wet Dry
- Parallel Dual Amp Modelers
- Stereo Parallel FX Loops
- Mono Parallel Effects Loop
- Blend Dual Tube Amps
- Serial to Parallel Effects Loop
- Stereo Analog Dry Thru
- Mono Analog Dry Thru

HX Stomp - Wet Dry Wet

Strymon Iridium - Wet Dry Wet

Walrus ACS1 - Wet Dry Wet

Kemper - Wet Dry Wet



Dirty - Wet Dry Wet

Clean - Wet Dry Wet

Dual Delay - Wet Dry Wet

Dirty - Wet Dry

Clean - Wet Dry

Parallel - Wet Dry

Parallel Dual Amp Modelers

Stereo Parallel FX Loops

Mono Parallel Effects Loop

Blend Dual Tube Amps

Serial to Parallel Effects Loop



Stereo Analog Dry Thru

Mono Analog Dry Thru