

# Routing Options

Wiring diagrams for various signal routing options.

- HX Stomp - Wet Dry Wet
- Strymon Iridium - Wet Dry Wet
- Walrus ACS1 - Wet Dry Wet
- Kemper - Wet Dry Wet
- Dirty - Wet Dry Wet
- Clean - Wet Dry Wet
- Dual Delay - Wet Dry Wet
- Dirty - Wet Dry
- Clean - Wet Dry
- Parallel - Wet Dry
- Parallel Dual Amp Modelers
- Stereo Parallel FX Loops
- Mono Parallel Effects Loop
- Blend Dual Tube Amps
- Serial to Parallel Effects Loop
- Stereo Analog Dry Thru
- Mono Analog Dry Thru

# HX Stomp - Wet Dry Wet



# Wet



# Walrus ACS1 - Wet Dry Wet



# Kemper - Wet Dry Wet



# Dirty - Wet Dry Wet





# Clean - Wet Dry Wet



# Dual Delay - Wet Dry Wet





# Dirty - Wet Dry



# Clean - Wet Dry



# Parallel - Wet Dry



# Parallel Dual Amp Modelers





# Stereo Parallel FX Loops




# Mono Parallel Effects Loop





# Blend Dual Tube Amps



# Serial to Parallel Effects Loop



# Stereo Analog Dry Thru



# Mono Analog Dry Thru

